



Installation instructions for the Leica TL2 - Firmware 1.1

Dear Customers,

By installing the firmware 1.1 on your Leica TL2 a bug fix issue will be solved.

Update Contents

Model Number	LEICA TL2
Update Version	Version 1.1
Update File Name	TL2_1100.LFU

Firmware Update Procedure

1. Copy the firmware file onto a SD Memory Card in its top level folder.
2. Make sure to turn off the power switch on the camera.
3. Insert the fully charged battery to the body. If the battery is not fully charged, the update process screen will not appear.
4. Insert the SD Memory Card into the camera.
5. Turn the camera – while simultaneously pressing the video release button – on.
6. The firmware update screen will appear. Press OK.
7. The LEICA TL2 will start the update process. The firmware update will take about 90 seconds.
8. After the update process please restart the camera.

CAUTION:

Please do **not** turn off your camera, or do **not** remove the SD Memory Card, do **not** remove the lens while updating your camera's firmware.

DOING SO CAN CAUSE A SERIOUS DAMAGE TO YOUR CAMERA!